


New Gaslifter Mark 10X-117-3-15-15-POD6 & Channel Products

*RECOMMENDED SPARK GAP 3/32" TO 5/32"



Connection diagram for replacement gaslifter
Old existing wires (with female connectors) to be
connected together with the wires of the new
gaslifter (male connectors) according to the
diagram. NOTE! the flame probe is not needed
when using this new gaslifter. Remove the old
wire (SENS) totally.